

.015625 -----	1/64	
.03125 -----		1/32
.046875 -----	3/64	
.0625 -----		1/16
.078125 -----	5/64	
.09375 -----		3/32
.109375 -----	7/64	
.125 -----		1/8
.140625 -----	9/64	
.15625 -----		5/32
.171875 -----	11/64	
.1875 -----		3/16
.203125 -----	13/64	
.21875 -----		7/32
.234375 -----	15/64	
.25 -----		1/4
.265625 -----	17/64	
.28125 -----		9/32
.296875 -----	19/64	
.3125 -----		5/16
.328125 -----	21/64	
.34375 -----		11/32
.359375 -----	23/64	
.375 -----		3/8
.390625 -----	25/64	
.40625 -----		13/32
.421875 -----	27/64	
.4375 -----		7/16
.453125 -----	29/64	
.46875 -----		15/32
.484375 -----	31/64	
.5 -----		1/2
.515625 -----	33/64	
.53125 -----		17/32
.546875 -----	35/64	
.5625 -----		9/16
.578125 -----	37/64	
.59375 -----		19/32
.609375 -----	39/64	
.625 -----		5/8
.640625 -----	41/64	
.65625 -----		21/32
.671875 -----	43/64	
.6875 -----		11/16
.703125 -----	45/64	
.71875 -----		23/32
.734375 -----	47/64	
.75 -----		3/4
.765625 -----	49/64	
.78125 -----		25/32
.796875 -----	51/64	
.8125 -----		13/16
.828125 -----	53/64	
.84375 -----		27/32
.859375 -----	55/64	
.875 -----		7/8
.890625 -----	57/64	
.90625 -----		29/32
.921875 -----	59/64	
.9375 -----		15/16
.953125 -----	61/64	
.96875 -----		31/32
.984375 -----	63/64	
1. -----		1.